



RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		LEGAL DESCRIPTION		LOT 143 SOUTHWATE #1			
3441 JOLA CIRCLE				3441 JOLA CIRCLE					
INSPECTION AREA		FIRE ZONE		BUILDING BY		DATE			
5				BARBARO		5/11/67			
FINAL INSPECTIONS		BUILDING BY		ELECTRICAL BY		DATE		DATE	
				BARBARO		5/11/67			
GEN. CONTR.		ELEC. CONTR.		PLBG. CONTR.		MECH. CONTR.		ARCH. ENGR.	
ROBIN CO.									
TITLE AND NAME		ADDRESS		CITY LIC. NO.		TEL. NO.		ELECTRICAL BY	
1/C						HI7-3072		DATE	
OWNER		541 S. TYLER, EL MONTE, CALIF.		CERTIFICATE OF OCCUPANCY		ISSUED BY		DATE	
HARBOUR HOUSE & GARDEN									
SIDE YARDS		REAR YARDS		SET BACK REQ.		USE ZONE		PARK'G REQ.	
						R-1		SPACES	
BLDG. WIDTH		BLDG. LENGTH		TOTAL HEIGHT		NO. OF STORIES		AREA 1st FLOOR	
						ROOMS		1,365 sq. Ft.	
EXISTING BLDG'S SAME LOT		TREES RMVD.		HOW USED		EXISTING BLDG'S SAME LOT		460 GAR.	
						C.S.D.		C.I. CASE	
CENSUS TRCT. NO.		TOTAL AREA		NO. OF STORIES		TOTAL HEIGHT		BLDG. WIDTH	

NATURE OF WORK:- CONST., DWLG., & GAR.

ISSUED BY	PERMIT NO. S.P. -	D-4279
ISSUANCE DATE	12/16/59	
VALUATION	\$	13,100.
R.D.F. FEE	\$	
JOB FILE	REEL NO.	64
INSPECTION RECORD	REEL NO.	64
	FRAME NO.:-	169
	TO	170
	FRAME NO.:-	132
	TO	148
	FRAME NO.:-	
	TO	
PLANCK. FEE	\$	
SEWER INCL. FEE	\$	
PERMIT FEE	\$	38.50
TOTAL FEES	\$	

REMARKS AND/OR VARIANCES

517-1145 - [Handwritten signature]