

*R 243 F402*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$5.00**

**TYPE BUILDINGS**

PERMIT NO. <b>G-1141</b>		LOCATION <b>523 - Sandburg Drive A-1 (1)</b>			
DATE <b>Aug-7-68</b>		PURPOSE <b>Repair pest damage to dwelling.</b>			
ZONE <b>R-1</b>		OWNER <b>Bader Same</b>			
		ARCH'T <b>483-5386</b>			
		CONT'R <b>Dales Termite Control 2330 - Butano Dr.</b>			
VAL. <b>\$300.</b>		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	PHONE (O) (C)
FORM					
JOIST					
FRAME SHEET ROCK	<b>8-8-68</b>	<b>Barlato (shower)</b>			
FINAL	<b>12-9-68</b>	<b>Perlo</b>			

<b>DATE</b>	<b>SPECIAL CONDITIONS OF WORK — REMARKS</b>
<b>COMPLETE AND OK</b>	<b>INSPECTOR</b>