

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10-526</i>	LOCATION <i>3236 - Riverside</i>			
DATE <i>7/13/42</i>	PURPOSE <i>Repairs to dwg due to fire</i>			
ZONE	OWNER <i>E. J. Goret</i>			
	ARCH'T.			
	CONT'R. <i>Chas Vanina</i>			
VAL. <i>16000</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
7/17/42	1 ST /HSP. Forms for 2 Wing Admns & sub gdnly O.K. AW Campbell
8/5/42	2 ND /HSP. France ^{OK} AW Campbell
8/2/42	3 RD /HSP. PATCHING OF LATH & PLASTER ^{INTERIOR LATH & ST} AW Campbell
8/21/42	4 TH /HSP. Additional Repairs Completed O.K.
8/24/42	COMPLETE AND O. K. <i>Allen W Campbell</i> INSPECTOR