

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-29764</i> DATE <i>7-20-50</i> ZONE	LOCATION	<i>5390-Princeton Lane</i>
	PURPOSE	<i>Erect only</i>
	OWNER	<i>McKeller & Kelly</i>
	ARCH'T.	
	CON'TR.	<i>Owner</i>

VAL <i>\$ 4100</i>	STORIES	ROOMS	APTS.	SIZE
--------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
8-8-50	Forms <i>M.A. Shumway</i>
9-28-50	Frame (Bad joints in Gorge) <i>M.A. Shumway</i>
12-18-50	Final <i>M.A. Shumway</i>
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>