

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10,596</i>	LOCATION <i>504 T. ST</i>			
DATE <i>8/11/42</i>	PURPOSE <i>Make Repairs and Install New Foundation</i>			
ZONE <i>Gen. Com</i>	OWNER <i>C. MARTINEZ</i>			
	ARCH'T.			
	CONTR. <i>ELTON BLAIR</i>			
VAL. <i>460⁰⁰</i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
8/17/42	1 st /asp. Forms for New Concrete Foundation under old dwlg. J. K. A.W. Campbell
	2 nd /asp. frame for repairs to underpinning and choring up main floor. A.W. Campbell
11/23/42	4 th /asp. Repairs to Dwlg Completed
11/23/42	<p data-bbox="303 874 439 915">COMPLETE AND O.K.</p> <p data-bbox="526 853 1195 957"><i>Alden W. Campbell</i></p> <p data-bbox="1211 895 1354 915">INSPECTOR</p>