

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <u>B-3935</u>	LOCATION <u>1117 - Jernight Way</u>
DATE <u>9/30/39</u>	PURPOSE <u>Erect new dwl. garage</u>
ZONE <u>V 1st</u>	OWNER <u>R. W. Blankenburg</u>
	ARCH'T. <u></u>
	CONTR. <u>Owner</u>

VAL. <u>6600<sup>00</sup></u>	STORIES <u>1</u>	ROOMS <u>6</u>	APTS.	SIZE
-------------------------------	------------------	----------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<u>Area</u>
VENT SHAFTS		BOILER ROOMS	<u>1590<sup>00</sup></u>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<u>@ 350</u>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK—REMARKS
10/15/39	1 <sup>ST</sup> INSP. FORMER IN PLACE <sup>OK</sup> RW Campbell
1/16/40	2 <sup>ND</sup> INSP. FRAME " " <sup>OK</sup> RW Campbell
1/11/40	3 <sup>RD</sup> INSP. EXT. LATH <sup>OK</sup> RW Campbell
2/5/40	3 <sup>RD</sup> INSP. INT. LATH <sup>OK</sup> RW Campbell
	<p data-bbox="302 859 430 906">COMPLETE AND O. K.</p> <p data-bbox="1141 875 1277 906">INSPECTOR</p>