

BUILDING DIVISION BUILDING INSPECTOR'S REPORT CARD

48		TYPE BUILDINGS	
PERMIT NO. B-9333	LOCATION 576 - Swanston Dr.	PURPOSE Erect new dwg. & gar.	OWNER Henry Seiden
DATE 10/14/41	ARCH'T. C. E. Shuler	CONTR. C. E. Shuler	
ZONE -	VAL. 4000	STORIES 2	ROOMS 5
			APTS. 4
			SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	Area
VENT SHAFTS		BOILER ROOMS	1060'
OWNER'S INSPECTOR		SPRINKLER SYSTEM	@ 3.52
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
10/24/41	1 ST /HSP. Forms in place ^{OK} A.W. Campbell
12/1/41	2 ND /HSP. Frame ^{OK} A.W. Campbell
12/15/41	3 RD /HSP. INT + EXT LSTR ^{OK} A.W. Campbell
2/10/42	4 TH /HSP. Drivg + Garage Completed ^{OK}
2/10/42	COMPLETE AND O. K. <i>Allen W. Campbell</i> INSPECTOR