

K 232 F 234

Lot 875		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD				\$55.00
Glenbrook #9		TYPE BUILDINGS		<i>R229 F OR -70</i>		
PERMIT NO.		LOCATION				
<i>P-9430</i>		<i>69 - Waterglen Circle A-1 (52)</i>				
DATE		PURPOSE				
<i>1-30-68</i>		<i>Const. dwlg. : att. gar. Plan 101</i>				
ZONE		OWNER				
<i>R-1</i>		<i>Wilbrook, Inc. 2777-Alvarado St.</i>				
ARCH'T		San Leandro, Calif.				
CONT'R		383-9315				
VAL \$15,100.		STORIES	ROOMS	APTS.	SIZE	
		<i>1</i>	<i>5</i>	<i>462 gar.</i>	<i>1,525 sq. ft.</i>	
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP		PHONE (O) (C)	
FORM	<i>2-9-68</i>	<i>Surgeon</i>				
JOIST	<i>2-27-68</i>	<i>Field</i>				
FRAME	<i>3-21-68</i>	<i>Carbato</i>				
SHEET ROCK	<i>3-27-68</i>	<i>Field</i>				
FINAL	<i>5-10-68</i>	<i>Perlo</i>				

DATE	SPECIAL CONDITIONS OF WORK — REMARKS	
2-16-69	PK Slab - Not ready	Rialto
2-19-69	PK slab	Rialto
3-19-69	Frame - Not ready	Rialto
	COMPLETE AND OK	INSPECTOR