

## BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-14238</i>	LOCATION <i>6261-5<sup>th</sup> Ave</i>			
DATE <i>9/12-145</i>	PURPOSE <i>Erect new dwg. - par</i>			
ZONE	OWNER <i>Manuel Tabata-</i>			
	ARCH'T.			
	CONT'R. <i>Owner</i>			
VAL. <i>2500<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>	
VENT SHAFTS		BOILER ROOMS	<i>900<sup>00</sup></i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
10/12/25	1 <sup>ST</sup> HSP Firms for New Drive Garage <sup>OK</sup> A.W. Campbell
11/23/25	2 <sup>ND</sup> HSP Firms for <sup>K</sup> <del>drive</del> <del>garage</del> A.W. Campbell
11/23/25	3 <sup>RD</sup> HSP EXT. LATH <sup>OK</sup> A.W. Campbell

COMPLETE  
AND O. K.

INSPECTOR