

(2) 202 7173

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD** \$10.00

**TYPE BUILDINGS**

<b>PERMIT NO.</b> W-2796		<b>LOCATION</b> 2350 - Broadway		A-2	
<b>DATE</b> Sept 2-66		<b>PURPOSE</b> Wreck 1 service station			
		<b>OWNER</b> Richfield Oil		same	
<b>ZONE</b>		<b>ARCH'T</b>			
		<b>CONTR</b> Markwart Const.		4801-24th St.	
<b>VAL.</b>		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>		<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b> 456-4741
<b>FORM</b>					
<b>JOIST</b>					
<b>FRAME</b>					
<b>SHEET ROCK</b>					
<b>FINAL</b>	10/5/66	Kerle			

A

ent

<b>DATE</b>	<b>SPECIAL CONDITIONS OF WORK — REMARKS</b>
<b>COMPLETE AND OK</b>	<b>INSPECTOR</b>