

R32 PE 133-141

| | | | | | |
|-----------------|----------|--|-----------------|---------------|----------|
| Lot 502 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | | \$123.00 |
| Sierra Oaks #15 | | TYPE BUILDINGS | | | |
| PERMIT NO. | | | | | |
| H-6803 | LOCATION | 2087 - Morley Way | | A-1 (1) | |
| DATE | PURPOSE | Const. dwelling & att. garage | | | |
| May-5-72 | OWNER | Mr. & Mrs. Dave Knight 3782 - Breuner | | | |
| ZONE | ARCH'T | /Ave. | | | |
| R-1 | CONT'R | J. C. Britton 4900 - Oak Vista Drive | | | |
| VAL. \$36,900. | STORIES | ROOMS | APTS. | 612-gar. SIZE | |
| | 1 | | | 2,492 sq.ft. | |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| | | | | 481 903 | |
| FORM | 5-11-72 | Fuller | | | |
| JOIST | 5-23-72 | Blumman | | | |
| FRAME | 6-21-72 | Grupe | | | |
| SHEET ROCK | 6-27-72 | Seymour | | | |
| FINAL | 8-21-72 | Blumman | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|--|
| 5-19-72 | L. Joist. not ready <i>Harmon</i> |
| 5-26-72 | P. sp. not ready <i>Harmon</i> |
| | |
| | |
| | |
| | |
| | |
| | |
| | <p>COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p> |