

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD


TYPE BUILDINGS

PERMIT NO. B-40473	LOCATION	911 Santa Ynez Way		
DATE 5-3-54	PURPOSE	Repair Fire Damage		
ZONE	OWNER	C. Daringer		
	ARCH'T			
	CONT'R	Charles Vanina		
VAL. 5,000	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	INSPECTOR		
FORM				
JOIST				
FRAME	Did not call for insp	Don W Berry.		
LATH				
FINAL	12-9-54	Don W Berry.		

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
	COMPLETE AND OK
	INSPECTOR