

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-5650</i>	LOCATION <i>3124 - San Diego Way</i>
DATE <i>2/10/37</i>	PURPOSE <i>Erect new dwlg. & Garage</i>
ZONE	OWNER <i>Clarence Neely</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL. <i>3300⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS		BOILER ROOMS	<i>1120⁰¹</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 3⁰²</i>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
3/20.37	1 st Jump Formed at 100 feet
4/13.37	2 nd Jump Formed at 100 feet
4/20 37	3 " " " " " " " "
6/11.37	4 th Jump Formed at 100 feet
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>