

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
3-23-73	Bldg. \$6,700.00	A-2125 \$60.00	Const.addn.& convert /ptn.of attic for dwlg.	Judi L. Carmen	Owner 537-Blackwood	<i>Vasti</i>	8-27-73
12-3-71	Bldg.\$500	<i>I 16585</i> H-4537 \$24.	Reapir termite damage	Carnes	<i>Harrod 9.11.73</i> Crest Termite Co.	<i>Collins</i> COURT	8-27-73 6-22-73
4-17-80	BMPE \$6703.00	H-2560 \$140.00	Room Add Dw1..	C. Carnes Same	Owner	<i>Seras</i>	3/19/82 BMPE
5-30-80	E \$250.00	H-3671 \$20.00	ChangeElect Service Dw1.H-13248	C. Carnes Same	Owner	<i>NASCA</i>	2.15.83

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
A-2125	<i>R 248 F 112</i>				
A-2125	R 363 F 66-67				
H-4537	R 316 F 130 <i>R 375 F 193</i>				
H-2560	<i>R 620 F 347</i>				
H-3671	<i>D 625 F 412</i>				
H-2560	<i>R 726 F 397-99</i>				
H-3671	<i>R 786 F 293</i>				

final.
found

