

R168 7501-504

Lots 11&12 BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$67.00

Blk. 18

South Sacramento

TYPE BUILDINGS

R174 7348-File

| | | | | | |
|----------------|--|-----------------------|--|--|--|
| PERMIT NO. | | LOCATION | | A-1 | |
| F-552 | | 3641 - 2nd Avenue | | | |
| DATE | | PURPOSE | | Const. fndn. & make struc. repairs for | |
| May 13-65 | | OWNER | | James Chandler 4551-12th ^{480 unit} moved apts. | |
| ZONE | | ARCH'T | | James Dodd 2014-28th St. / Ave. | |
| R-4 | | CONT'R | | Ed Avila 3724-36th St. 451-2738 | |
| VAL. \$20,000. | | STORIES | | APTS. 1390-2nd fl SIZE | |
| | | | | 4 un = 1130 sq. ft. | |
| INSP. | | BLDG. TYPE | | OCCUPANCY GROUP | |
| DATE | | | | PHONE (O) (C) 1860 sq. ft. | |
| FORM | | | | 6 un = 2060-2nd fl. | |
| JOIST | | | | | |
| FRAME | | | | | |
| SHEET ROCK | | | | | |
| FINAL | | Partial Final Insults | | Ant. Com. (P) | |
| 7-23-65 | | J. J. [Signature] | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS | |
|---------|--|-----------|
| 5-17-65 | PT Load - one more #4 horizontal bar required 2nd joist | Barbato |
| 5-17-65 | OK (fastening) | Barbato |
| 5-24-65 | PT Letdown - not ready | Barbato |
| 5-26-65 | OK let down | Barbato |
| 6-2-65 | ①. nailing not as per plans. Metal ties incorrect | Barbato |
| 6-3-65 | Remail joist to middle OK. | Barbato |
| 6-3-65 | Punches - 20' of force | Barbato |
| 2-5-66 | 10' - 10' long pit | Barbato |
| | | |
| | COMPLETE AND OK | INSPECTOR |