

P-242 F-401

BUILDING DIVISION **BUILDING INSPECTOR'S REPORT CARD** \$10.00

TYPE BUILDINGS

| | | | | | |
|---------------------|----------------------|--|-------|-----------------|---------------|
| PERMIT NO. G-967 | | LOCATION 1055 - Teneighth Way A-2 (24) | | | |
| DATE July-19-68 | | PURPOSE Repair pest damage to dwelling. | | | |
| ZONE R-1 | | OWNER Wiesler Same | | | |
| | | ARCHT 451-2242 | | | |
| | | CONTR Camellia Termite Co. 4311 - Franklin | | | |
| VAL. \$600. | | STORIES | ROOMS | APTS. | /Blvd. SIZE |
| INSP. | DATE | BLDG. TYPE | | OCCUPANCY GROUP | PHONE (O) (C) |
| FORM | | | | | |
| JOIST | | | | | |
| FRAME SHEET ROCK | | | | | |
| FINAL | <i>9-8-68 Larsen</i> | | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|--|
| 7.23.68 | OK chaves pan Rialo |
| 7.26.68 | Hammers does not in plates fenders of chaves # 6 not done. Remove from from crawl hole Lansin |
| 9.5.68 | At final - not done Hammers |
| | |
| | |
| | |
| | |
| | <div style="display: flex; justify-content: space-between;"> COMPLETE AND OK INSPECTOR </div> |