

D104 7203 - 207

## BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00

## TYPE BUILDINGS

|                        |  |               |                    |                     |  |
|------------------------|--|---------------|--------------------|---------------------|--|
| PERMIT NO.<br>E-1759   | LOCATION 210 - East Sandburg Drive A-1   |               |                    |                     |  |
| DATE<br>Jul 12-62      | PURPOSE Const. playroom to rear of dwlg. |               |                    |                     |  |
| ZONE<br>R-1            | OWNER<br>Dr. W. G. Peyton                |               | Same               |                     |  |
|                        | ARCH'T                                   |               |                    |                     |  |
|                        | CONT'R<br>Owner                          |               | GL 6-9802          |                     |  |
| VAL. \$700.            | STORIES                                  | ROOMS         | APTS.              | SIZE<br>450 sq. ft. |  |
| INSP.                  | DATE                                     | BLDG.<br>TYPE | OCCUPANCY<br>GROUP |                     |  |
| FORM                   |  |               |                    |                     |  |
| JOIST                  |  |               |                    |                     |  |
| FRAME<br>SHEET<br>ROCK | 8-3-62                                   | J. Barabato   |                    |                     |  |
| FINAL                  | 10-2-62                                  | J. Barabato   |                    |                     |  |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|------|--------------------------------------|
|      |                                      |
|      |                                      |
|      |                                      |
|      |                                      |
|      |                                      |
|      |                                      |
|      |                                      |
|      |                                      |
|      |                                      |
|      | COMPLETE AND OK                      |
|      | INSPECTOR                            |