

BUILDING DIVISION - BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. NO CHARGE PERMIT	LOCATION Service Station 3031 P. St	
	PURPOSE Make Repairs to Stucco Front of Bldg	PHONES
DATE Nov 25 1931	OWNER SAC TO SUPER SERVICE STATION #4	
ZONE General Commercial	ARCH'T	
CONT-R OWNER		

VAL.	6000	STORIES	1	ROOMS		APTS.		SIZE	
------	------	---------	---	-------	--	-------	--	------	--

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
11/23/31	3 rd WSP. Ext Lath for Repairs for Re-Shedding Front of Service Station Bldg OK
	A.W. Campbell
	COMPLETE AND O.K. INSPECTOR