

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-22095</i>	LOCATION <i>501 - Lutter Way.</i>			
DATE <i>5/5/48</i>	PURPOSE <i>Erect new dwlg. w garage</i>			
ZONE	OWNER <i>W. G. Pierce</i>			
	ARCH'T.			
	CONT'R. <i>J. Banducci.</i>			
VAL. <i>5420<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	<i>1084<sup>00</sup></i>
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
5/11/48	Forms <del>Added</del> Insp. <del>Added</del>
6/12/48	Frame " " "
10/21/48	Final " " "
	<div style="display: flex; justify-content: space-between;"> <span>COMPLETE AND O. K.</span> <span>INSPECTOR</span> </div>