

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|------------------------------|---|
| PERMIT NO. <i>B-11155</i> | LOCATION <i>1421-5th Street</i> |
| DATE <i>2/31/43</i> | PURPOSE <i>Repairs to flooring dwlg.</i> |
| ZONE <i>—</i> | OWNER <i>Fong Kong</i> |
| | ARCH'T. <i>—</i> |
| | CONT'R. <i>Chas Venina</i> |

| | | | | |
|------------------------------|---------|-------|-------|------|
| VAL. <i>160⁰⁰</i> | STORIES | ROOMS | APTS. | SIZE |
|------------------------------|---------|-------|-------|------|

| | | | |
|-------------------|--|------------------|--|
| LIGHT SHAFTS | | ELEVATOR SHAFTS | |
| VENT SHAFTS | | BOILER ROOMS | |
| OWNER'S INSPECTOR | | SPRINKLER SYSTEM | |
| LATH | | GAS VENTS | |
| FIRE ESCAPES | | CHIMNEYS | |
| STAND PIPES | | SKYLIGHTS | |

| DATE | CONDITION OF WORK—REMARKS |
|------|--|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | <p data-bbox="301 865 427 906">COMPLETE AND O. K.</p> <p data-bbox="1113 885 1253 916">INSPECTOR</p> |