

R234 F149

| | | | | | |
|----------------------|---|--|-----------------|---------------------|----------------------|
| Lot 883 | | BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD | | | \$49.00 |
| Glenbrook Unit 9 | | TYPE BUILDINGS | | | <i>R221 F132-139</i> |
| PERMIT NO. F-9734 | LOCATION 39 - Waterglen Circle A-1 (52) | | | | |
| DATE 3/8/68 | PURPOSE | Const. dwelling and garage #400-LS | | | |
| | OWNER | Sonya Corp. 2777 Alvarado St. San Leandro | | | |
| ZONE R-1 | ARCH'T | | | | |
| | CONT'R | Besco same 383-9315 | | | |
| VAL. \$13,500. | STORIES | ROOMS | APTS. | SIZE 1376 sq.ft. | |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| FORM | <i>3-21-68</i> | <i>Perkins</i> | | | |
| JOIST | <i>4-5-68</i> | <i>Field</i> | | | |
| FRAME | <i>5-7-68</i> | <i>Field</i> | | | |
| SHEET ROCK | <i>5-17-68</i> | <i>Field</i> | | | |
| FINAL | <i>6-21-68</i> | <i>Perkins</i> | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS | |
|---------|--------------------------------------|-----------|
| 3-29-68 | Rk slab | Risks |
| 4-1-68 | RT Brick - Luvix | Risks |
| 4-3-68 | RT Brick - not used | Risks |
| | | |
| | | |
| | | |
| | | |
| | | |
| | COMPLETE AND OK | INSPECTOR |