

## BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>None</i> <i>(Repairs)</i>	LOCATION <i>911 MISSION WAY</i>
DATE <i>Sept 20</i> <i>1932</i>	PURPOSE <i>Re-Roof Dwg with Composite Shingles</i>
ZONE <i>2-Family</i>	OWNER <i>GUY PATTERSON, 911 MISSION WAY</i>
	ARCH'T
	CONT-R <i>J. E. IRVINE 1816-51<sup>ST</sup> ST</i>

VAL.

*7700*

STORIES

ROOMS

APTS.

SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK—REMARKS
	COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span>