

R112 F120

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$13.00

TYPE BUILDINGS *Rep. fire damage*
R112 F120-209

PERMIT NO. E-9665		LOCATION 920$\frac{1}{2}$ - 5th Street		A-2	
DATE Feb. 24-65		PURPOSE Rep. fire damage & inst. fire escape			
ZONE C-3		OWNER C. Yasumato 637-Piedmont Dr/to hotel.			
		ARCH'T			
		CONT'R Owner		Same 421-2237	
VAL. \$2,000.		STORIES 3	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE III-1 hr.		OCCUPANCY GROUP H-1	PHONE (O) (C)
FORM					
JOIST					
FRAME					
SHEET ROCK					
FINAL					

S. L. ...

DATE

SPECIAL CONDITIONS OF WORK — REMARKS

*Hotel damaged by fire on 8-2-66
See photo log file*

COMPLETE
AND OK

INSPECTOR