

8987310

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD #5.00**

**TYPE BUILDINGS**

PERMIT NO.					
E-1019		LOCATION 1923 - 5th Street		A-2	
DATE		PURPOSE Repair stair jack to dwlg.			
Apr:10-62		OWNER Ysabel Nava		Same	
ZONE		ARCH'T			
R-1		CONT'R Owner		Same WA 7-1762	
VAL. \$100.		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE		OCCUPANCY GROUP	
FORM					
JOIST					
FRAME					
SHEET ROCK					
FINAL	8-17-62	Dana Fuller			



DATE	SPECIAL CONDITIONS OF WORK — REMARKS
COMPLETE AND OK	INSPECTOR

