

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>A-5287</i>	LOCATION <i>3808 - 2nd Ave.</i>			
DATE <i>11/23/36</i>	PURPOSE <i>Remodel Work</i>			
ZONE	OWNER <i>James S. Bishop</i>			
	ARCH'T			
	CONTR. <i>Quincy</i>			
VAL. <i>186600</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
12-31	2 <sup>nd</sup> Insp Frame on Rector
1-14	3 " Lock " Rector
<p>COMPLETE AND O. K.</p>	<p>INSPECTOR</p>