

## RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
3/5/65	Bldg. \$8,500.00	E-9810\$34.00	Const. new balcony in church sanctuary	Fremont Church	Chas F. Unger	Barbato	4/6/65
3/1/65	Bldg. \$1,800.00	E-9743	Const. storage for Church	Fremount Pres. Ch.	Chas Unger	Barbato	4/23/65
3/17/65	Bldg. \$200.00	E-9955\$5.00	Const. base house Trailer	Freemount Ch.	Owner	Chapin	8/3/65
1/20/66	Bldg. \$319,400	F-2885\$439.	Addn. classroom & social Hall;	Fremount Church	Nimbus Const.	Fuller	7/17/67
7/15/66	Bldg. \$14,500	F-4813\$52.	Const pass way for church	Nimbus Const.	Fremount Church	Fuller	6/8/68
12/15/66	Bldg. \$700.00	F-6069\$10.00	Const. office part. in ch.	Fremount Church	Owner	Fuller	6/8/67
5/16/72	Bldg. \$1,200.00	H-7076\$18.00	Reroof Church	Fremount Church	Owner	Fuller	8/28/72
12/5/75	Bldg. \$3,100.	C-9984\$39.	Reroof dwlg.	Fremount Church 5770 Carlson	Fred B. Curtis Inc. 1801 30th St.	NO FINAL INSPECTION CALLED BY PERMITEE.	
7/22/76	Bldg. \$900.00	D-5664\$15.00	Reroof dwelling	Fremount Church	Fred B. Curis 3 <sup>1</sup> / <sub>8</sub>	NO FINAL INSPECTION CALLED BY PERMITEE.	
5/9/77	Bldg. \$926.00	E-3225 \$30.00	Installation of Rudglas GLX 100-200 N/C Commer. Hot water heater	Fremount Pres. Church	Ray O. Cook, Mech. 5534 Elvas Ave.	Reynoso	8/3/77

## MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
E-9810	R-162F-442-443	F-4813	R-199F-21-222	E-3225	R-481F-255
E-9810	R-482F-292-final	F-4813	R-226F-442	E-3225	R-489F-485-final
E-9743	R-492-F-292-final	F-4813	R-492F-291-final	C-9984	Ⓟ 615F265 closed
E-9743	R-492 F-292-final	F-6069	R-207F-597-598	n-side 4	Ⓟ 615F265 closed
E-9955	R-492F-292-final	F-6069	R-492F-292-final		
E-9955	R-163F-397	H-7076	R-329F-99		
F-2885	R-185F-269-316	H-7076	R-492F-291-final		
F-2885	R-221F-298-300	C-9984	R-431F-044		
F-2885	R-492F-291-final	D-5664	R-450F-617		

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		5770 Carlson Drive		INSPECTION AREA		A-1	
LEGAL DESCRIPTION		N.W. Corner Carlson Dr. & H-St 18x9 R 566E		OCCUP. GR.		CONST TYPE		VAR. NO.	
TITLE AND NAME		C.F. Unger Const		ADDRESS		2112 Sutterville Road		TEL. NO.	
GEN. CONTR.		ELEC. CONTR.		PLBG. CONTR.		MECH. CONTR.		ARCH. ENGR.	
OWNER		Freemount P. Church		3600 J Street		CERTIFICATE OF OCCUPANCY		ISSUED BY	
BLDG. WIDTH		BLDG. LENGTH		TOTAL HEIGHT		NO. STORIES		ROOF CONSTR.	
SIDE YARDS		REAR YARDS		SET BACK REQ.		USE ZONE		PARK'G REQ.	
SPACES		TREES RMVD.		EXISTING BLDG'S SAME LOT		HOW USED			

NATURE OF WORK:-  
Const Church and attached Classrooms.

ISSUED BY		PERMIT NO. S.P. E-121	
PLANS AND APPLICATION		REEL NO. 96	
INSPECTION RECORD		REEL NO. 124	
JOB FILE		REEL NO.	
R.O.F. FEE		\$	
S.M.I. FEE		\$	
PLAN CK. FEE		\$	
SEWER INCL. FEE		\$	
PERMIT FEE		\$ 699.00	
TOTAL FEES		\$	

REMARKS AND/OR VARIANCES

R#92P303 - Jma

PLANS AND APPLICATION	FRAME NO. 289	TO	382
INSPECTION RECORD	FRAME NO. 353	TO	363
JOB FILE	FRAME NO.	TO	