

BUILDING DIVISION - BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>P-7397</i>	LOCATION <i>963 Robertson Way</i>			
DATE <i>1/27/41</i>	PURPOSE <i>Front Office Bldg. & Detached Garage</i>			
ZONE <i>2-FAMILY</i>	OWNER <i>DAVID HILL, 3222 T. St. Carson</i>			
CONTR. <i>OWNER</i>	ARCH'T.			
VAL. <i>5000⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS. <i>1</i>	SIZE <i>32'-9" x 47'</i>
LIGHT SHAFTS	ELEVATOR SHAFTS		<i>1411 Sq Ft NET</i>	
VENT SHAFTS	BOILER ROOMS			
OWNER'S INSPECTOR	SPRINKLER SYSTEM			
LATH	GAS VENTS			
FIRE ESCAPES	CHIMNEYS			
STAND PIPES	SKYLIGHTS			

DATE	CONDITION OF WORK—REMARKS
1-27-41	1 ST Jump Forming OK <i>OK</i>
2/26/41	2 ND INSP. Frame in place <i>OK</i>
2/28/41	3 RD INSP. INT & EXT LATH <i>OK</i>
	<p data-bbox="278 833 406 875">COMPLETE AND O. K.</p> <p data-bbox="1106 849 1235 875">INSPECTOR</p>