

1187496-504

Lot 158 BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$58.00

Greenhaven Unit #1 TYPE BUILDINGS

| | |
|----------------------|--|
| PERMIT NO. E-3475 | LOCATION 97 - Moonlit Circle A-3 |
| DATE Mar 19 1963 | PURPOSE Const. 2 story dwlg. & att. gar. |
| ZONE R-1 | OWNER Jan L. Warnshuis 4816-Donovan Dr. Carm. |
| | ARCH'T CONT'R Diamond Homes P.O. Box 1, Carmichael |

| | | | | |
|----------------|--------------|------------|-------------------|-----------------------|
| VAL. \$16,500. | STORIES 2 | ROOMS 7 | APTS. 500 gar. | SIZE 1,710 sq. ft. |
|----------------|--------------|------------|-------------------|-----------------------|

| | | | | |
|------------|----------------|--------------------|-----------------|---------------------------|
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) 964-3269 |
| FORM | <i>4-10-63</i> | <i>Fulles</i> | | |
| JOIST | <i>4-24-63</i> | <i>Fulles</i> | | |
| FRAME | <i>5-22-63</i> | <i>Bird</i> | | |
| SHEET ROCK | <i>6-3-63</i> | <i>Fulles</i> | | |
| FINAL | <i>7-29-63</i> | <i>M. Calloway</i> | | <i>MC</i> |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|---|
| 4.5.13 | Pt (mudcell) not laid out of bearings don't comply with 4.9.13 |
| 4.9.13 | Clean out pipe fittings only 12" into ground neck will be left |
| 4.19.13 | Pt. Excessive vibrations Pt. Motor piece repaired. |
| 4.22.13 | no wind at stage. Be-Drill. |
| 9.26.13 | Pt. mudcell on gas Pt. Driveway, work on main (open road & cuttings, 3' water on from side) |
| | |
| | |
| | |
| | COMPLETE AND OK |

INSPECTOR