

B 1197 278

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$13.00

TYPE BUILDINGS

PERMIT NO. E-3573		LOCATION 5890 - South Land Park Drive A-3			
DATE Apr 2-63		PURPOSE Remodel 2nd floor for dance studio			
ZONE C-1		OWNER Dr. T. Holstein 2912-Capitol Ave.			
		ARCH'T See E-1730			
		CONTR Gilbert Const 1637-Gary Way, Carm.			
VAL. \$1,100.		STORIES	ROOMS	APTS.	SIZE 1,850 sq. ft.
INSP.	DATE	BLDG. TYPE III no hr.		OCCUPANCY GROUP B-3	PHONE (O) (C) IV 3-8133
FORM					
JOIST					
FRAME	<i>4-11-63</i>	<i>Lenders</i>			
SHEET ROCK	<i>4-16-63</i>	<i>Lenders</i>			
FINAL	<i>5-17-64</i>	<i>C. Thompson</i>			

*Ent. Em. Rep.
3-5-64*



DATE	SPECIAL CONDITIONS OF WORK — REMARKS
4.3.63	PT Plates with 2" washers. Needs
4.8.63	must be 16" o.c. Jullies PT show about metal studs in ceiling well? Count
4.9.63	PT framing incomplete. Blocking at ceiling line. & mid night Details
3.4.64	Occupied, send notice. Hammer
3.9.64	PT Contractor didn't keep appointment Hammer
	COMPLETE AND OK

INSPECTOR

