

ISSUED

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

JAN 30 1930

TYPE VII BUILDINGS

SACRAMENTO
BUILDING DIVISION

LOCATION

5032 U. ST.

PURPOSE

ROOMS

APTS.

DATE

Replace 7 Casement Windows with Double-Hung Windows New Garage Door
and make general repairs

OWNER

PHONE

JAN. 30 1930

OAKLAND BUILDING & LOAN CO

ARCH'T

ZONE

2-Family Dist

CONT'R

CAPITAL LUMBER CO

VAL.

STORIES

SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Joints						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
4/30/30	Made inspection of General Repairs being made to dwlg. Replaced 7 Casement Windows with 7 Double-Hung Windows, install new Garage Doors, and make general repairs to dwlg. O.K. A.W. Campbell All completed except exterior painting
COMPLETED AND O.K.	INSPECTOR