



RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS		INSPECTION AREA	
3700 Belden St.		6			
LEGAL DESCRIPTION					
Del Paso Hghts. Lot 12					
TITLE AND NAME		ADDRESS			
1/c		ZIP			
GEN. CONTR.		CITY LIC. NO.			
Owner		TEL. NO.			
ELEC. CONTR.		CENSUS TRCT. NO.			
PLBG. CONTR.		TOTAL AREA			
MECH. CONTR.		1,423			
ARCH. ENGR.		EXISTING BLDG'S SAME LOT			
OWNER		HOW USED			
Sissler Const.		2223 Dale Ave.			
CONST. LOAN LENDER		C.I. CASE			
BLDG. WIDTH		TOTAL HEIGHT		NO. OF STORIES	
BLDG. LENGTH		1		ROOF CONSTR.	
REAR YARDS		AREA 1st FLOOR		PARK'G REQ.	
SIDE YARDS		SPACES		TRES RMVD.	
SET BACK REQ.		USE ZONE		PARK'G REQ.	
1		1		SPACES	

NATURE OF WORK:- Const. dwelling & att. garage

ISSUED BY		MICROFILM RECORD	
PERMIT NO. S.P. - H-4157		PLANS AND APPLICATION	
ISSUANCE DATE 11-4-71		REEL NO. 501 TO 507	
VALUATION \$21,100.00		FRAME NO. 025- (Dmg) TO	
R.D.F. FEE \$		JOB FILE	
S.M.I. FEE \$		REEL NO. TO	
PLAN CK. FEE \$		FRAME NO. TO	
SEWER INCL. FEE \$		REMARKS AND/OR VARIANCES	
PERMIT FEE \$84.00		Dwelling	
TOTAL FEES \$			