

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS ~~R 4 16~~

PERMIT NO. <b>B-17414</b>	LOCATION <b>5954 - Raymond Way.</b>
DATE <b>10/20/46</b>	PURPOSE <b>Erect new stupa - gar</b>
ZONE	OWNER <b>John Fernandez</b>
	ARCH'T.
	CONTR. <b>Quincy</b>

VAL. <b>5370<sup>00</sup></b>	STORIES <b>1</b>	ROOMS <b>5</b>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS	<b>10740'</b>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
1/20/47	Farm Insp. O. E. Buckins
2-21-47	Farm Insp. H. E. Jones
	<div data-bbox="310 907 462 957" data-label="Text">COMPLETE AND O. K.</div> <div data-bbox="1268 924 1436 957" data-label="Text">INSPECTOR</div>