

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS ~~R 4 16~~

PERMIT NO. <i>B-17414</i>	LOCATION <i>5954 - Raymond Way.</i>
DATE <i>10/20/46</i>	PURPOSE <i>Erect new stupa - gar</i>
ZONE	OWNER <i>John Fernandez</i>
	ARCH'T.
	CONTR. <i>Quincy</i>

VAL. <i>5370⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
-------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS <i>10740'</i>
VENT SHAFTS	BOILER ROOMS
OWNER'S INSPECTOR	SPRINKLER SYSTEM
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK—REMARKS
1/20/47	Farm Insp. O. E. Buckius
2-21-47	Farm Insp. H. E. Jones
	<div data-bbox="310 907 462 957" data-label="Text"> <p>COMPLETE AND O. K.</p> </div> <div data-bbox="1268 924 1436 957" data-label="Text"> <p>INSPECTOR</p> </div>