

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA	FINAL INSPECTIONS		
		3064 Bridgeford Drive					A-6			
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY	DATE
Larchmont Northgate #2 Lot 140									Hammons	11-29-71
TITLE AND NAME			1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.	ELECTRICAL BY	DATE
GEN. CONTR. Owner										
ELEC. CONTR.									PLUMBING BY	DATE
PLBG. CONTR.										
MECH. CONTR.									MECHANICAL BY	DATE
ARCH. ENGR.										
OWNER Larchmont Northgate									CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER									ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE		
						467 GAR 1150 sq ft				
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	CENSUS TRCT. NO.	EXISTING BLDG'S SAME LOT	HOW USED	
			R-1							

NATURE OF WORK:- Const. dwelling and garage MP #234

PERMIT NO. S.P. - G-7618	MICROFILM RECORD				
ISSUED BY					
ISSUANCE DATE Jul-22-'70	PLANS AND APPLICATION	REEL NO. 285	FRAME NO. 385	TO	R267 F151-158 Plans
VALUATION \$ 17,800	INSPECTION RECORD	REEL NO. 10 P 5 98	FRAME NO. 385	TO	
R.D.F. FEE \$	JOB FILE	REEL NO.	FRAME NO. 385	TO	
S.M.I. FEE \$					
PLAN CK. FEE \$					
SEWER INCL. FEE \$					
PERMIT FEE \$	REMARKS AND/OR VARIANCES				
\$	Form: 8-14-'70 Riolo				
\$	Frame: 9-14-'70 Riolo				
TOTAL FEES \$ 68	Sheet Rock: 9-23-'70 Riolo				