

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS					INSPECTION AREA	FINAL INSPECTIONS	
		2224 Florin Road					5		
LEGAL DESCRIPTION					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.		
GEN. CONTR.	California Allied								
ELEC. CONTR.									
PLBG. CONTR.									
MECH. CONTR.									
ARCH. ENGR.									
OWNER	Victorville Land Dev.						CERTIFICATE OF OCCUPANCY		
CONST. LOAN LENDER								ISSUED BY	
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE	
						1224 sq.ft.	CENSUS TRCT. NO.		
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED	

NATURE OF WORK:- Const. dwlg. & gar.

PERMIT NO. S.P. -	C-820	MICROFILM RECORD		
ISSUED BY		PLANS AND APPLICATION	REEL NO. 900	FRAME NO:- 236
ISSUANCE DATE	1-13-55	INSPECTION RECORD	REEL NO.	FRAME NO:- TO
VALUATION	\$ 11,600.	JOB FILE	REEL NO.	FRAME NO:- TO
R.U.F. FEE	\$			
S.M.I. FEE	\$			
PLAN CK. FEE	\$			
SEWER INCL. FEE	\$			
PERMIT FEE	\$	REMARKS AND/OR VARIANCES		
	\$	Dwelling		
	\$			
TOTAL FEES	\$			

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FILED BY	DATE
7/16/76	B. \$ 1,100.00	D-5491 \$ 20	Re-roof	Dick Look Same	Owner Same	<i>Rolo</i>	8/10/76
8-3-76	Bldg. \$900.00	D-5995 \$15.00	Enclose carport to garage Dtlg.	Dick J. Look Same	Owner	<i>Rolo</i>	10/28/76 B

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
D-5491	4450R292				
D-5995	4451R487				
D-5491	4461R338				
D-5995	4461R338				