

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-4956-</i>	LOCATION <i>2633 - Riverside Blvd</i>
DATE <i>3/9/40</i>	PURPOSE <i>Erect new restaurant Bldg.</i>
ZONE	OWNER <i>Trinnis & Co</i>
	ARCH'T.
	CONTR. <i>Chas Vanina</i>

VAL <i>5000⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	<i>3 1/2</i>
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

LIMITED RETAIL ZONE OK

DATE	CONDITION OF WORK—REMARKS
3/11/40	1 ST INSPECTION. Forms for Mrs. Restaurant & Cafe Bldg. O.K. A.W. Campbell
3/23/40	2 ND INSPECTION. Forms in place O.K. A.W. Campbell
4/2/40	3 RD INSPECTION. EXT. LATE O.K. A.W. Campbell
4/12/40	4 TH INSPECTION. Cafe Bldg. Completed O.K. A.W. Campbell
4/14/40	COMPLETE AND O. K. A.W. Campbell INSPECTOR

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <i>No CHARGE</i>	LOCATION <i>2633 Riverside Blvd.</i>
DATE <i>APR. 6. 1933</i>	PURPOSE <i>Install 1 Outside Door 2 Windows + Outside Steps</i>
ZONE <i>Limited Retail</i>	OWNER <i>E. B. PERINI 2633 Riverside Blvd.</i>
	ARCH'T
	CONT-R <i>OWNER</i>

VAL.	<i>40⁰⁰</i>	STORIES	<i>1</i>	ROOMS		APTS.		SIZE
------	------------------------	---------	----------	-------	--	-------	--	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
4/6/33	Gave Owner this No CHARGE PERMIT for installing
	1. Outside Door, 2 Windows + Outside Steps to Soft
	Drink Place + Residence OK A.W. Campbell.
4/6/33	COMPLETE AND O. K. <i>Alden H Campbell</i> INSPECTOR