

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS 2748 Bridgedford Drive					INSPECTION AREA A-6	FINAL INSPECTIONS		
LEGAL DESCRIPTION Northgate Unit #9 Lot 1171					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY Fuller	DATE 9-3-70
TITLE AND NAME		V/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.		ELECTRICAL BY	DATE
GEN. CONTR.	Owner								PLUMBING BY	DATE
ELEC. CONTR.									MECHANICAL BY	DATE
PLBG. CONTR.										
MECH. CONTR.										
ARCH. ENGR.										
OWNER	Taylor-Mazza, Inc					CERTIFICATE OF OCCUPANCY				
CONST. LOAN LENDER							ISSUED BY		DATE	
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA 465 Gar. 1280 sq ft.	C.S.D.	C.I. CASE		
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE R-1	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT		HOW USED	

NATURE OF WORK: **Const. dwelling and garage MP #4-3**

PERMIT NO. S.P. G-6794	MICROFILM RECORD				
ISSUED BY					
ISSUANCE DATE May 13-70	PLANS AND APPLICATION	REEL NO. 281	FRAME NO. 234	TO	R281 F221-233 (Plans)
VALUATION \$ 19,600	INSPECTION RECORD	REEL NO. 4118326	FRAME NO. 327	Combone	
R.D.F. FEE \$	JOB FILE	REEL NO.	FRAME NO.	TO	
S.M.I. FEE \$					
PLAN CK. FEE \$					
SEWER INCL. FEE \$					
PERMIT FEE \$	REMARKS AND/OR VARIANCES				
\$	Form: 6-11-70 Calloway				
\$	Frame: 7-28-70 Riolo				
TOTAL FEES \$ 74	Sheet Rock: 7-30-70 Riolo				

