

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-13996</i>	LOCATION <i>3814 - West. Land Park Dr.</i>			
DATE <i>5/2/45</i>	PURPOSE <i>New dwlg. - garage</i>			
ZONE	OWNER <i>S. J. Borg.</i>			
	ARCH'T.			
	CONT'R. <i>John Koch</i>			
VAL. <i>7005⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		<i>1450^{sq ft}</i>
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
5/25/25	1 ST /HSP Forms for New Drive ^{OK} AW Campbell
10/2/25	2 ND /HSP Finance ^{OK} AW Campbell
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>