

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-82776</i>	LOCATION <i>270 - Livali Way</i>			
DATE <i>5/19/41</i>	PURPOSE <i>Erect new dwg & gar</i>			
ZONE <i>v-7am</i>	OWNER <i>L. B. Roland</i>			
ARCH'T.	CONTR. <i>John E. Roland</i>			
VAL. <i>3800⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS	BOILER ROOMS	<i>1017⁰¹</i>
OWNER'S INSPECTOR	SPRINKLER SYSTEM	<i>@ 342</i>
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
5/20/41	1 st Insp. Frame of <u>Paint</u>
1/18/41	2 nd Insp. Frame in place ^{OK} NW Campbell
	3 " <u>Lat</u> I T E of <u>Paint</u>
10/20/41	1 <u>Formal</u> of <u>Paint</u>

COMPLETE
AND O. K.

INSPECTOR