

*R283 F106*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$15.00**

**TYPE BUILDINGS**

PERMIT NO. <b>G-6978</b>	LOCATION <b>3017 - U Street A-2 (19)</b>
DATE <b>May-27-70</b>	PURPOSE <b>Repair pest damage to dwelling</b>
ZONE <b>R-1</b>	OWNER <b>Elizabeth Howard Same</b>
	ARCH'T <b>655-7955</b>
	CONT'R <b>Western Extermination 3906-Grove St.</b>

VAL. <b>\$1,400.</b>	STORIES	ROOMS	APTS.	SIZE
----------------------	---------	-------	-------	------

INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)
FORM	<i>6-5-70</i>	<i>Fallen</i>		
JOIST				
FRAME	<i>6-9-70</i>	<i>Roofs</i>		
SHEET ROCK				
FINAL	<i>11-17-70</i>	<i>J. Blumberg</i>		

<b>DATE</b>	<b>SPECIAL CONDITIONS OF WORK — REMARKS</b>
<b>COMPLETE AND OK</b>	<b>INSPECTOR</b>