

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS 6541 Harmon Drive				INSPECTION AREA 3	FINAL INSPECTIONS		
LEGAL DESCRIPTION Lot 21 S.L.P. Riviera #3				OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY Larsen	DATE 4/25/68
TITLE AND NAME		1/C	ADDRESS	ZIP	CITY LIC. NO.	TEL. NO.		ELECTRICAL BY	DATE
GEN. CONTR. Lee Basford			Owner						
ELEC. CONTR.								PLUMBING BY	DATE
PLBG. CONTR.									
MECH. CONTR.								MECHANICAL BY	DATE
ARCH. ENGR.									
OWNER Lee Basford			6660 Havenside Dr.					CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER								ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE	
					519-garage	1,847 sq. ft.		CENSUS TRCT. NO.	
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT		HOW USED

NATURE OF WORK:- **Const. dwlg. & att.garage**

PERMIT NO. S.P. - F-9146	MICROFILM RECORD			
ISSUED BY	PLANS AND APPLICATION	REEL NO. 230	FRAME NO:- 68	TO 77
ISSUANCE DATE 12/5/67	INSPECTION RECORD	REEL NO.	FRAME NO:-	TO
VALUATION \$ 18,000.00	JOB FILE	REEL NO.	FRAME NO:-	TO
R.D.F. FEE \$				
S.M.I. FEE \$				
PLAN CK. FEE \$				
SEWER INCL. FEE \$				
PERMIT FEE \$61.00				
\$				
\$				
TOTAL FEES \$				

R511F243 - final
REMARKS AND/OR VARIANCES
DWELLING

