

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-2853</i>	LOCATION <i>501 - Pala Way</i>			
DATE <i>4/13/39</i>	PURPOSE <i>Erect new duplex apt</i>			
ZONE <i>1</i>	OWNER <i>W. Ketherington</i>			
	ARCH'T. <i>Watson</i>			
	CONTR. <i>Bennie</i>			
VAL. <i>1450⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS		BOILER ROOMS	<i>1150⁰⁷</i>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE.	CONDITION OF WORK-REMARKS
4/20.39	16' Prop Frames on Piles
5/12.39	7 " Frame " Piles
	<p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p>