

*R 250 FNB*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**\$10.00**

**TYPE BUILDINGS**

Double Fee

*R 253 F409 file*

<b>PERMIT NO.</b>					
G-2014	<b>LOCATION</b> 3844 - Rose Street A-7 (65)				
<b>DATE</b>	<b>PURPOSE</b> Repair detached garage of dwlg. (dry rot etc)				
Nov-21-68	<b>OWNER</b> Chas. Morris 2736 - Del Paso Blvd.				
<b>ZONE</b>	<b>ARCH'T</b> No phone.				
R-1	<b>CONT'R</b> Owner Same				
<b>VAL.</b> \$300.		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
					500 sq. ft.
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>	<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>	
<b>FORM</b>					
<b>JOIST</b>					
<b>FRAME SHEET ROCK</b>					
<b>FINAL</b>	<i>12.3.68</i>	<i>Shapiro</i>			

<b>DATE</b>	<b>SPECIAL CONDITIONS OF WORK — REMARKS</b>
	<b>COMPLETE AND OK</b>

**INSPECTOR**