

R-99 FH68 Plans FH62-465

Lot 34 **BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD** \$46.00

Meadowview Gardens **TYPE BUILDINGS**

|                      |   |
|----------------------|---|
| PERMIT NO.<br>E-1215 | LOCATION 2041 - Quincy Avenue A-5   |
| DATE<br>May 1-62     | PURPOSE Const. dwelling & attached garage   |
| ZONE<br>R-1          | OWNER Harry J. Buckman III 1700- <del>E</del> St. Apt. #5<br>ARCH'T 1700-S <u>SI</u><br>CONTR Owner HI 7-6367 |

|               |              |            |                                   |      |
|---------------|--------------|------------|-----------------------------------|------|
| VAL \$12,900. | STORIES<br>1 | ROOMS<br>6 | APTS.<br>525 gar.<br>1318 sq. ft. | SIZE |
|---------------|--------------|------------|-----------------------------------|------|

| INSP.      | DATE    | BLDG. TYPE | OCCUPANCY GROUP     |
|------------|---------|------------|---------------------|
| FORM       | 5-8-62  | Jones      |                     |
| JOIST      | 5-18-62 | Callaway   |                     |
| FRAME      | 7-30-62 | Field      |                     |
| SHEET ROCK | 8-15-62 | Fulmer     |                     |
| FINAL      | 4-17-63 | Geo. Perlo | notice sent 4/14/63 |

| DATE    | SPECIAL CONDITIONS OF WORK — REMARKS  |
|---------|---|
| 7-20-62 | <p>St. James - All 2x6 ceiling joints must<br/> be nailed with 1x4 nailed on the top of each<br/> end. Two vent area repairs in<br/> two car garages. <i>Full</i></p> |
| 7-25-62 | <p>St. James - Wood ceiling hallway to be<br/> filled in. <i>Full</i></p>   |
| 1-24-63 | <p>Will call when ready for <i>Full</i></p>   |
| 4-3-63  | <p>St. Occupied without a permit<br/> send notice <i>Full</i></p>   |
| 1-10-63 | <p>COMPLETE Shower door in bath must be<br/> welded <i>Full</i> 4-24-63 <i>Full</i></p>   |

INSPECTOR