

5133 71-7

Lt. 8

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD

\$55.00

Greenhaven 70 Unit #1 TYPE BUILDINGS

| | | | | | |
|----------------------|----------------|--------------------------------------------|-----------------|----------------|-------------------------------|
| PERMIT NO. E-4780 | | LOCATION 379 - Parklin Avenue | | A-3 | |
| DATE Aug. 19-63 | | PURPOSE Const. dwelling & attached garage | | | |
| ZONE R-1 | | OWNER J. D. Slade 7235 - Chandler Drive | | ARCH'T | |
| | | CONTR Owner | | Same GA 8-9008 | |
| VAL \$15,500. | | STORIES 1 | ROOMS 6 | APTS. | 480-gar. SIZE 1,590 sq.ft. |
| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) | |
| FORM | <i>9-23-63</i> | <i>Decking</i> | | | |
| JOIST | <i>9-4-63</i> | <i>Joists</i> | | | |
| FRAME | <i>9-26-63</i> | <i>Frame</i> | | | |
| SHEET ROCK | <i>10-8-63</i> | <i>Sheetrock</i> | | | |
| FINAL | <i>12-4-63</i> | <i>Dana Fuller</i> | | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|--------------------------------------|
| 1931-63 | It must remove all broken and |
| | split mudells. Put level Bedrock |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK |

INSPECTOR