

RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.		JOB ADDRESS 23-Glenville Circle				INSPECTION AREA 1		FINAL INSPECTIONS		
LEGAL DESCRIPTION Lot 1028 Glenbrook #10					OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE	BUILDING BY Barbato	DATE 10/2/68
TITLE AND NAME		1/C	ADDRESS		ZIP	CITY LIC. NO.	TEL. NO.		ELECTRICAL BY	DATE
GEN. CONTR. Besco			Same San Leandro, Cal.							
ELEC. CONTR.									PLUMBING BY	DATE
PLBG. CONTR.										
MECH. CONTR.									MECHANICAL BY	DATE
ARCH. ENGR.										
OWNER Center Dev.			2777-Alvarado Street						CERTIFICATE OF OCCUPANCY	
CONST. LOAN LENDER									ISSUED BY	DATE
BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE		
					447-garage	1,327 sq. ft.		CENSUS TRCT. NO.		
SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT		HOW USED	

NATURE OF WORK:- **Const. dwelling & attached garage Plan 402**

PERMIT NO. S.P. - G-721	MICROFILM RECORD			
ISSUED BY				
ISSUANCE DATE	PLANS AND APPLICATION	REEL NO. 240	FRAME NO:- 407	TO
VALUATION \$	INSPECTION RECORD	REEL NO. 180	FRAME NO:- 491	TO 501
R.U.F. FEE \$	JOB FILE	REEL NO.	FRAME NO:-	TO
S.M.I. FEE \$				
PLAN CK. FEE \$				
SEWER INCL. FEE \$				
PERMIT FEE \$				
\$				
\$				
TOTAL FEES \$				

R507P650 - final

REMARKS AND/OR VARIANCES
DWELLING

