


BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <b>7791</b>	LOCATION <b>74 Land Dr Terrace 1190 Parkside Ave</b>			
DATE <b>3/18/31</b>	PURPOSE <b>FR W or 1/2 6 Room Dup Garage</b>			
ZONE <b>2 Fam.</b>	OWNER <b>L M Collins</b>			
	ARCH'T <b>Russell Lark</b>			
	CONT-R <b>Tom Merrill</b>			
VAL. <b>6000</b>	STORIES <b>2</b>	ROOMS <b>6</b>	APTS. <b>1</b>	SIZE <b>36 x 34 - 2</b>

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
3/21-31	1 <sup>st</sup> Insp Forms in place for P.H. Hunter
4/23-31	2 " Frame " " " P.H. Hunter
4/29-31	3 " At Test " " P.H. Hunter
8/1-31	4 " Finalled for Certificate
	of occupancy issued at Cl. up
	<div style="display: flex; justify-content: space-between; align-items: center;"> <div data-bbox="330 879 503 933">COMPLETE AND O.K.</div> <div data-bbox="578 786 1156 977" style="text-align: center;">  </div> <div data-bbox="1205 906 1395 933">INSPECTOR</div> </div>