CITY OF SACRAMENTO 1231 I Street, Sacramento, CA 95814

Site Address: 8645 WEST WING DR SAC

Parcel No:

SHELDON WHITEHOUSE PH 1 LOT # 64

CONTRACTOR
CENTEX HOMES
2527 CAMINO RAMON STE. #250
SAN RAMON, CA 94583

OWNER

ARCHITECT
RITNER ARCHITECHTURAL GROUP
20201 SW BIRCH ST. STE. 150
NEWPORT BEACH, CA 92660

Permit No: 0509463

Sub-Type: NSFR


Insp Area: Thos Bros:

Housing (Y/N): N

Nature of Work: MP936 1 STORY 4 RM HALF PLEX

	N LENDING AGENCY s permit is issued (Sec. 309	 I hereby affirm under po 77, Civ. C). 	enalty of perjury that t	there is a construction	n lending agenc	y for the performance of
Lender's Name	NIA		dnder's Address			
LICENSED CON (commencing with sec	ction 7000) of Division 3 of	RATION: I hereby affithe Business and Profession	ns Code and my licens	se is in full force and	licensed under placed in the second in the s	provisions of Chapter 9
License Class	License Number 82594	3 Date 7 191	Contractor Sign	gnature_Du	stai Str	aure-
reason (Sec. 7031.5, E prior to its issuance, a License Law (Chapter	Business and Professions C lso requires the applicant for 9 (commencing with Sect exemption. Any violation of	I hereby affirm under penal ode; any city or county which is such permit to file a signe ion 7000) of Division 8 of the fraction 7031.5 by any apparent.	th requires a permit to d statement that he or he Business and Profe	o construct, alter, im she is licensed pursessions Code) or that	prove, demolish suant to the prov at he or she is ex	, or repair any structure, isions of the Contractors tempt therefrom and the
sale (Sec. 7044, Busir who does such work h	ness and Professional Code nimself or herself or through	oyees with wages as their so: The Contractors License he his/her own employees, pear of completion, the owner.	Law does not apply to rovided that such imp	an owner of proper provements are not it	rty who builds o ntended or offer	r improves thereon, and ed for sale. If, however,
The Contractors Licenticensed pursuant to the	ise Law does not apply to a ne Contractors License Law	•	سمحاه محريم سينست سيادات	eon, and who conte	SIACH TURN proj	ects with a contractor(s)
I am exempt ur	nder Sec	B &PC for this reason:_	<u>.</u>	CHYON	L 19 200	5
Date		Ower Signature		S IC N	राम गाउँ	ALT
measurements and loo private agreement rela improvement or the vi	cations shown on the applating to permissible or prololation of any private agree	e applicant represents, and to cation or accompanying dra hibited locations for such in ment relating to location of	awings and that the inprovements. This built improvements.	representation of the mprovement to be of uilding permit does	capplicant that constructed does not authorize an	the applicant verified all into violate any law or only illegal location of any
		that all information is corre entative(s) of this city to ente				
Date 7/19	105	Aplicant/Agent Signatu	rre Dobbu	Stantes		
I have and will		ARATION: I hereby affire consent to self-insure for world.				
I have and will this permit is issued.	maintain workers' comper My workers' compensation	isation insurance, as require insurance carrier and policy	d by Section 3700 of number are:	the Labor Code, fo	r the performan	ce of the work for which
Carrier ZU	URICH AMERICAN INSU	R Polic	y Number WC8322	097-08	Exp Date	10/01/2005
not employ any persor	n in any manner so as to be	permit is for \$100 or less) come subject to the worker 0 of the Labor Code, I shall	s' compensation laws	of California and ag		
Date 7/10	105	♣plicant Signature	Debh	i Stou		

WARNING: FAILURE TO SECURE WORKER'S COMPENSATION COVERAGE IS UNLAWFUL AND SHALL SUBJECT AN EMPLOYER TO CRIMINAL PENALTIES AND CIVIL FINES UP TO ONE HUNDRED THOUSAND DOLLARS (\$100,000) IN ADDITION TO THE COST OF COMPENSATION, DAMAGES AS PROVIDED FOR IN SECTION 3706 OF THE LABOR CODE, INTEREST AND ATTORNEY'S FEE.



OR Ceneral Contractor (Co. Name) OR Owner

WATER HEATING SYSTEMS

Heater Type	CEC Certified Mfr Name & Model #	Discriptions Type (Sul- point of use)	If Recirculation Control Type	# of Identical Systems	(2) Rased Input (kW or Bas/hr)	Tank Volume (gullone)	(2) Efficiency (EF,RE)	(1) Standby Lass (%)	Enternal Insulation Revalue
Cond S	beadford which H-1-50SbFBD	CA.	N/H	MA	40,000	_50_	-67-	<i>t</i> /4_	N/A

- (2) For small gas storage (mind laput of less than or equal to 75,000 Justin), electric resistance and thest pump water heaters. But Energy Factor, For large gas storage water heaters (raised input of greater than 75,000 Biufir), list Recovery Efficiency. Standby Loss and Rated Input. For losis attacous gas water heaters, list Recovery officiency and Rated Input.
- (1) R-12 external insulation is mandatory for storage water heaters with an anongy factor of less that 0.5%.

Facets & Shower Header

Art flucits and showarheads installed are contribed to the Commustion, pursuant to Title 24, Part 6, Section 113.

I, the undersigned, verify that equipment listed above my signature (x.1) the setuel equipment installed; 1) equivalent to or more efficient dish that specified in the certificate of compliance (Form CF-1R) submitted for compliance with the finergy Afficiency Standardsfor residential buildings; and 3) equipment that meets or exceeds the appropriate requirements for manufactured devices (from the Appliance of English where applicable.

COPY TO: Building Department HERS Provider (if appricable) **Building Owner at Occupancy**

Signature, Date

B2- A. v. a. B. v. Co., Localling Subcontractor (Co. Name)
OR General Contractor (Co. Name) OR Owner

INSTALLATION CERTIFICATE

CF-6R

Centex - Serenade

Permit Number 0509463

Site Address BG45 WEST WING DR An installation certificate is required to be posted at the building site or made available for all appropriate inspections. (The information provided on this form is required; however, use of this form to provide the information is optional.) After completion of final inspection a copy must be provided to the building department (upon request) and the building owner at occupancy, per Section 10-103(b).

HVAC SYSTEMS:

Heating Equipment

1100mmild -1							Heating	
Equip. Type (pkg.	CEC Certified Mfr name	# of Identical (i) Efficiency (AFUR, etc.) > CF-1R value	Duct Location (artic, etc.)	Duct or Fiping R-value	Heating Load (Btu/br)	Capacity (Bm/hr)	May 1778
Heat pump) Furnace Furnace Furnace Furnace	and Model # Lennox G40UH-36A-70 Lennox G40UH-48B-90 Lennox G40UH-60C-110 Lennox G40UH-60C-110		0.80 0.80 0.80 0.80	Attic Attic Attic Attic	R-6.0 R-8.0 R-6.0 R-6.0	29,167 31,809 31,744 37,986 37,061	70,000 90,000 90,000 110,000	Plan 1776 Plan 1841 Plan 2242 Plan 2444 Plan 2806 Plan 5 Unit 1
Fumace Fumace	Lennox G40UH-36A-70 Lennox G40UH-36A-70	l	0.80	Attic Attic	R-6.0 R-6.0	19.489 21,556	70,000	Plan 5 Unit 2
Cooling Equip. Type (pkg. Heat pump)	CBC Certified Compresso Unit Mfr Name and	r w of Identical Systems	(i) Efficiency (SEER cm.) > CF-1R Value	Duct Location (autic, etc.)	Duct Revalue	Cooling Load (Hearly)	(But/pt)	Plan 1776
Condenser Condenser Condenser	Lennox 13ACC-038 * Lennox 13ACC-048 * Lennox 13ACC-048 * Lennox 13ACC-080 *		13.0 13.0 13.0 13.0	Attic Attic Attic Attic Attic	R-6.0 R-6.0 R-6.0 R-6.0	24,632 25,300 24,689 30,695 30,695	30,500 31,400 41,900 48,700 48,700	Plan 1841 Plan 2242 Plan 2444 Plan 2806 Plan 5 Unit 1
Condenser Condenser	Lermox 13ACC-024*		13.0 13.0	Attic	R-6.0 R-8.0	18,901 22,231	21.500 27.600	Plan 5 Unit 2

*TXV - Indicates Thermal Expansion Valve On Coll

(1) \geq reads greater than or equal to. I, the undersigned, varify that equipment listed above is: 1) is the actual equipment installed, 2) equivalent to or turns efficient than that specified in the certificate of compliance (Form CF-IR) submitted for compliance with the Energy Efficiency Sundards for residential buildings, and 3) equipment that meets or exceeds the appropriate requirements for manufactured devices (from the applicance Efficiency Regulations or Part 6), where emplicable.

3-19-05

Beutler Corporation

OR General Contractor (Co. Name) OR Owner

WATER HEATING SYSTEMS:

	CEC Certified Mfr	Distribution Type (Std. point of use)	If Recirculation. Control Type	# of Identical Systems	(3)Rated Input (kW or Bto/hr)	Teok Volume (gallons)	(2) Efficiency (EF,RE)	(2) Standby Loss (%)	Insulation R-value
Heater Type	Name & Model #	point of one							

- (2) For small gas storage (rated input of less than or equal to 75,000 Burlst), electric resistance and heat pump water heaters, list Energy Factor. For large gas storage water beaters (rated input of greater than 75,000 Bin/ln), first Recovery Efficiency, Standby Loss and Rated Input. For instantaneous gas water heaters, list Recovery efficiency and Rated input.
- (3) R-12 external translation is mandatory for storage water heaters with an energy factor of less that 0.58.

Facets & Shower Hends:

All facets and showerheads installed are certified to the Commission, pursuant to Title 24, Part 6, Section 111.

I, the undersigned, varify that equipment listed above my signature is: 1) the actual equipment installed; 2) equivalent to or more efficient than that specified in the certificate of compliance (Form CP-1R) submitted for compliance with the nergy Efficiency Sundards for residential buildings; and 3) equipment that recets or expectes the appropriate requirements for manufactured devices (from their fluores Efficiency Regulations of Part 6), where applicable.

Signature, Date

Installing Subcontractor (Co. Name) OR General Contractor (Co. Name) OR Owner

COPY TO: Building Department

HERS Provider (if applicable) Building Owner at Occupancy




	DATE: //-2-05	DS	DSA FILE/APPL. NO.									
PROOF LOAD	PROJECT NO. 2007	<u>os</u>	OSHPD NO.									
PROOF LOAD TORQUE WITNESSING Testing was performed on the following items. All tests were performed with the following calibrated equipment: RAM:	PROJECT: ENTE	PE	PERMIT NO.									
Testing was performed on the following items. All tests were performed with the following calibrated equipment: RAM:	LOCATION: SERENADE LOT-64			WEATHER: TEMP;								
Testing was performed on the following items. All tests were performed with the following calibrated equipment: RAM:	☐ PROOF LOAD	TORQUE	K	WITN	ESSI	NG						
RAM: GAGE: TORQUE WRENCH: COCATION OF TEST TYPE / SZZE TESTED TOTAL COCATION OF TEST TOTAL COCATION OF TES		*										
RAM: GAGE: TORQUE WRENCH: LOCATION OF TEST TYPE / SIZE TESTED TOTAL LOCAD B GAGE PSD ACC REJ RETEST						-	· ·	-				
Type of epoxy grout used: Set 3587 72 Excellent of the best of my knowledge, the above WAS WAS NOT performed in accordance with the approved plans, specifications, and regulatory requirements.												
Type of epoxy) grout used: Septical SET 72 / EX. 16. Method of application / cleaning: All / Septical Set 72 / EX. 16. Method of application / cleaning: All / Septical Set 72 / EX. 16. Method of application / cleaning: All / Septical Set 72 / Septical Set 74 / Set 75 / Septical Set 75 / Septiminary Septiminary Septiminary Set 75 / Septiminary Set 75 / Septiminary Set 75 / Septiminary Set 75 / Septiminary Septiminary Set 75 / Septiminary Septiminary Set 75 / Septiminary Septi	LOCATION OF TEST		TYPE / SIZE			LOAD Ib						
Visual inspection was performed on		,							1			
Visual inspection was performed on												
Visual inspection was performed on										}		
Visual inspection was performed on												
Visual inspection was performed on												
Visual inspection was performed on				<u> </u>								
Visual inspection was performed on												
Visual inspection was performed on					i							
Visual inspection was performed on					I							
Visual inspection was performed on		•	$t = s_t$									
Visual inspection was performed on		.										
All non-compliance items were brought to the attention of: NON-COMPLIANCE REPORT ATTACHED ADDITIONAL TESTS ATTACHED NOTES: To the best of my knowledge, the above WAS / WAS NOT performed in accordance with the approved plans, specifications, and regulatory requirements.	Visual inspection was per	formed on <u>IHE</u> PRE-DRINE	LACENIE D AND	\mathcal{N}/\mathcal{L}	DF_1	HICEL	control contro	4)x 0)x 4X	12"1	3,RUS) CHGR EMB R		
NON-COMPLIANCE REPORT ATTACHED ADDITIONAL TESTS ATTACHED NOTES: To the best of my knowledge, the above WAS / WAS NOT performed in accordance with the approved plans, specifications, and regulatory requirements.	Show up / Stand by time	. Job Canceled / Del	ayed due to: _									
NON-COMPLIANCE REPORT ATTACHED ADDITIONAL TESTS ATTACHED NOTES: To the best of my knowledge, the above WAS / WAS NOT performed in accordance with the approved plans, specifications, and regulatory requirements.	☐ All non-compliance items	were brought to the atte	ention of:						at the	iob site.		
	NON-COMPLIANCE REPORT	ATTACHED [_							,		
			····			· "						
	To the head of much service of the s											
Superintendent/Representative: Inspector		S / WAS NOT performed	in accordance	with the app	proved pla	ans, specifica	tions, and re	gulator	/ requir	ements.		
	Superintendent/Representative:	;	Inspe	ctor								
		* · · *	i		$I \prec$	et.						
					+							

3121 Diablo Avenue Hayward CA 94545 4741 Pell Drive #8 Sacramento GA 95838 520 Mercantile Street #A Cotati, CA 94931

310 W 5th Street #203 Santa Ana CA 92701

JOB SITE COPY





WEST WING DRIVE

LEGEND

AC UNIT LOCATION \boxtimes

DRAIN INLET

SEWER SERVICE

WATER SERVICE

Ø STREET LIGHT

A **TRANSFORMER**

U UTILITY BOX

STREET LIGHT SERVICE POINT

FIRE HYDRANT

STOP SIGN

to make any changes or alterations from The approval of this plan and specificati SHALL NOT be held to permit or approve same without written permission Building Inspection Division. violation of any City Ordinance or State on the Job at all times and it is unless

DON

N WHITEHOUSE CENTEX HOMES PLOT PLAN FOR LOT 64

APN:

LOT AREA: 3,176 S.F.

ADDRESS: 8645 WEST WING DRIVE CALIFORNIA CITY OF SACRAMENTO

6/16/2005 1212.003 Jobs/1212-Sheidan-Whitehouse\Sheidan-Whitehouse Phase 1\Civil\Plotplan\LOT 64.dwg

6/16/05