



BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>H-5571</i>	LOCATION <i>3236 - Riverside Blvd</i>			
DATE <i>1/23</i>	PURPOSE <i>Erect new double garage</i>			
ZONE <i>2-Jan</i>	OWNER <i>Mrs. M. Gort</i>			
	ARCH'T.			
	CONT'R. <i>Quincy H.C. Prince in charge of work</i>			
VAL. <i>2600⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>4</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>	
VENT SHAFTS		BOILER ROOMS	<i>2600⁰⁰</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 30%</i>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
4/30/37	1 ST INSP. Frame in place ^{OK} A.W. Campbell
5/20/37	2 ND INSP. Frame ^{OK} A.W. Campbell
6/11/37	3 RD INSP. INT & EXT WALLS ^{OK} A.W. Campbell
7/28/37	4 TH INSP. Dura Condition
" "	Issued Final Insp & Certificate of Occupancy
" "	Shut cleaned up ^{OK} 
7/28/37	COMPLETE AND O. K.  INSPECTOR