

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-17.</i>	LOCATION <i>533 - San Antonio Way.</i>			
DATE <i>3/4/38</i>	PURPOSE <i>Erect new dwlg. & garage</i>			
ZONE	OWNER <i>Herman Metzner</i>			
	ARCH'T.			
	CONTR. <i>Frank Williams -</i>			
VAL. <i>2650⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS	
3/19/38	1st	Jump Frames of Ruster
3/20/38	2	" " Frames " Ruster
3/29/38	2	" " " " Ruster

COMPLETE
AND O. K.

INSPECTOR